


## R64PT




☐ the marked items are consumables  
[not covered by any guarantee]

1 04P09002	12 04P00707	23 04P09003	34 04P00725
2 04A00237	13 04A00217	24 04P09005	35 04P00726
3 04P00701	14 04P00714	25 04P09007	36 04P00727
4 04P00704	15 04P00715	26 04P09008	37 04A00240
5 04P00732	16 04P00716	27 04P09010	38 04F00100
6 04P00053	17 04P00721	28 04P09011	39 04P00720
7 04P00702	18 04P00717	29 04P09012	40 04P00733
8 04P00703	19 04A00218	30 04P09013	42 04P00625
9 04A00216	20 04P00713	31 04P00722	43 04P00626
10 04P00706	21 04A00219	32 04P00723	
11 04P00705	22 04P00622	33 04P00724	



# Q-TOOL R64PT



## Technical information

**Capacity** Standard Blind rivets Ø 3.0/3.2 | 4.0 | 4.8/5.0 |  
6.0 | 6.4 mm

Structural Blind rivets Ø 4.8 | 6.4 mm

**Material** Aluminum, Steel and Stainless Steel


**Size** 440 [L] x 180 [H] mm

**Weight** 1.75 kg

**Stroke** 7.0 mm

### Description of the tool

- |                                |                |
|--------------------------------|----------------|
| 1 Left (black) and right lever | 4 Tool Body    |
| 2 Nosepiece 6,4 mm ID mark H   | 5 Lock Nut     |
| 3 Mandrel collector            | 6 Front sleeve |



### Blind rivets: standard

- B 3.0/3.2 mm  
C 4.0 mm  
E 4.8/5.0 mm  
G 6.0 mm

### Structural rivets: M-Power

- J 4.8 mm  
L 6.4 mm

### Structural rivets: Q-Split-Power

- K 4.8 mm  
M 6.4 mm



## Instructions

### Opening the box

The hand tool will be standard equipped with the 6.4 mm nosepiece. The other nosepieces are stored in the lever of the tool. A smaller set of jaws is stored in the box, including 1 x spanner for changing the nosepiece.

### First use

Make sure before using the tool that the correct nosepiece is installed on the tool. Otherwise change to a different nosepiece.



### 1 - Change to a different nosepiece

Close the left and right lever [1] completely. In this way the jaws and internal spring are released. Use the spanner to unscrew the nosepiece. Replace it by choosing the correct nosepiece for your selected blind rivets and release the levers [1] again.

### 2 - Cleaning or changing the jaws

Close the left and right lever [1] completely. Loosen the lock nut [5] and unscrew the front sleeve [6]. When the lock nut is taken off, open up the levers completely until they click. By doing this, the clamping sleeve with Jawset, pusher, push pin spring, puller assembly and the return spring will be released from the tool [B1]. Cover the items with your hand before doing this, because due to the force of the spring below, it can come out with some force. Now you can unscrew the clamping sleeve and change or clean the jaws. Afterwards, reassemble by reversing the above procedure. For the reassembling of drawing B1, just reassemble according to picture B1, and push it back into the tool.

### 3 - Setting a blind rivet

Put the tool in start position by opening the levers up to maximum. There is a clicking sound. The jaws will open completely and the ratchet mechanism is unlocked. Insert the blind rivet into the nosepiece and slide into the hole of the material. The hole size must be slightly larger than the rivet, check the specification of rivet. Close the levers completely once to activate the ratchet mechanism. Now open the levers for one third till you hear the clicking sound of the mechanism, then close the levers completely. Repeat these steps until the maximum breaking load has exceeded and the mandrel will break. Open the levers up to maximum, until the clicking sound, the ratchet mechanism is unlocked and the rest mandrel will fall into the mandrel collector [3]. Empty the mandrel collector after setting 50 blind rivets.

**Important!** After having started setting the rivet do not open the levers completely anymore before the rivet has been set. When levers have been opened completely before having set the rivet, the ratchet process has to be started again.

